

## Wiring Diagram for Stratocaster 5-way Wiring Harness

All my Strat harnesses are mounted on a genuine Fender Aluminum Ground shield which you will mount under your pickguard. This shield acts as your common ground, so you do not need the ground wire that runs from pot to pot.

When you receive your harness, you will notice that I have left the Jack still soldered to the white and black wire. You will have to un-solder it before you install the harness. I hook up the jack whilst building it, so as I can test the harness by hooking it up to a test guitar on my bench. I leave it soldered up, so you can see which wire goes to which lug. You wouldn't believe how many buyers wire it up the wrong way around.

I also include the black wire from the volume pot to the tremolo claw which is shown in blue on the wiring diagram.

### **Please scroll down to the next page for the wiring diagram**

I now include a short black ground wire from the Volume pot. Use this wire to hook up the 3 ground wires from the pickups.

This eliminates the possibility of you overheating the volume pot. There is no longer a need to solder the 3 pickup ground wires to the back of the volume pot.

My harnesses are mounted on a genuine Fender Aluminum shield which you will mount under your pickguard. This shield acts as your common ground so you do not need the ground wire that runs from pot to pot.

